

iBA KİMYA SAN. ve TİC. A.Ş. 1. Organize Sanayi Bölgesi Oğuz Caddesi No:22 06930 Sincan / Ankara / Türkiye Tel:+90312 267 09 83 Fax:+90312 267 09 87 www.iba.com.tr

FF88

Technical Data Sheet

Description

FF88 is a thermosetting powder based on epoxy and polyester resins that provide satin finishes with outstanding flowout and resistance to over bake yellowing.

Characteristics

Available for all colours One coat finishes Suitable for most indoor environments Less waste and pollution to the environment Decorative film appearance by good flow out

Applications

Office furniture Lighting equipment Shelves

Product Properties

UV Resistance	Not recommended for exterior use.	
Flow out	Very good	
Surface	Matt CM – Semimatt CS – Wrinkle WR	
Specific gravity	vity 1.5-1.8 gr/cm3 (low with dark colours, high with light colours)	
Shelf Life	12 months (< 30°C and < 50% RH)	

Application Data

Application Curing	Corona (Can be applied by tribo guns if product code has "T" for the 6th character) 200°C 10 minutes recommended*			
	Metal Temperature (°C)	Time (minutes)	¥,	
	190	15-25	*	
	200	8-18		
	210	6-14	*	
			96 200 200 200 200 200 20	
Film Thickness	60-80u (recommended)**	k		

Film Thickness 60-80µ (recommended)**

Theoretical cons. 8-10 m²/kg. Practical spreading rates will vary due to such factors as method and conditions of application, specific gravity, surface profile and texture.

*180°C curing, catallized version is available.

**Recommended film thickness for WR coded products is 80-130µ, theoretical consumption value should be calculated due to this thickness range.



iBA KİMYA SAN. ve TİC. A.Ş. 1. Organize Sanayi Bölgesi Oğuz Caddesi No:22 06930 Sincan / Ankara / Türkiye Tel:+90312 267 09 83 Fax:+90312 267 09 87 www.iba.com.tr

FF88

Coating Properties

Test results shown below are based on 0.5 mm steel with 60μ applied powder coatings.

Direct Impact	>40 kgcm	(ISO 6272-2)
Reverse Impact	>20 kgcm	(ISO 6272-2)
Buchholz Hardness	>90	(ISO 2815)
Conical Mandrel	0 mm	(ISO 6860)
Cross Hatch Adhesion	Gt:0	(ISO 2409)

** Mechanical properties may decrease for WR coded products due to higher film thickness values.

Application Guide

Surface Preparation

All surfaces should be degreased and pretreated for optimal performance. Suitable pretreatment includes:

Aluminium	Yellow chromate or green chromate/phosphate
Ferrous metals	Zinc phosphate or Iron phosphate
Zinc Coated Metals	Zinc phosphate or chromate

Application Procedure and Equipment

FF88 series powder coatings charging properties are optimized when powder is free-flowing and moisture-free. Aged or compacted powder may require preconditioning for several minutes to fluidise evenly.

If storage room temperature is lower than the application area, powder coatings, which are hygroscopic, should be acclimated in unopened containers prior to adding into the spray hopper. For optimum performance, It should be applied and stored at air-conditioning area. Storage temperatures should be kept below 30°C.

Powder should not be stored in hoppers for long periods of time. If moisture condensation occurs, fluidize powder to dry-out or replace moisture-laden powder with virgin powder.

Powder coatings are finely ground particulates. Respirators or dust masks should be used by workers exposed to powder in order to avoid dust inhalation.

Compressed air to the gun must be oil and moisture free.

Silicone should not be used in application area.

For box feeders, ensure probe is fully inserted in powder and operated as per manufacturer's recommendations.

Contact points should be maintained to ensure metal-to-metal ground.

Apply by electrostatic spray. Relative humidity should be 50-60% for corona system, lower than 40% for tribo system. Cure as per recommendations outlined above.

Reclaim-to-virgin ratios should be carefully monitored to maintain spray consistency.

Sieving powder before adding to hopper eliminates potential clumping or foreign matter.

Test for cure of the coating by impact test.

Care and Maintenance

FF88 should be regularly washed with warm water and mild liquid detergent, followed by a fresh water rinse to maintain the attractive appearance of the powder cured film.

The use of abrasive cleaners is not recommended, nor is the use of active organic solvents.



IBA KİMYA SAN. ve TİC. A.Ş. 1. Organize Sanayi Bölgesi Oğuz Caddesi No:22 06930 Sincan / Ankara / Türkiye Tel:+90312 267 09 83 Fax:+90312 267 09 87 www.iba.com.tr

FF88

Health and Safety

The SDS is an integral part of using this product as it contains information on the potential health effect of exposure, personal protective equipment needed. It is recommended to contact to Sales and Customer Service Offices for further information.

Precautions and Limitations

As a result of possible wide application variations and stoving conditions, **FF88** may show variation, between İBA Kimya Powder Coatings prepared samples and production applied material. Therefore, it is the applicator and/or their customer's responsibility to ensure the product conforms to their requirements.

For optimum performance ensures recommended dry film thickness is obtained.

Not recommended for use in highly corrosive environments.

Not recommended for exterior applications.

The gloss may vary depending on the heating rate of the substrate.

Yellowing can be occur at light colors when left in the oven for a long time.

Transport and Storage

Packaging	15-20-25 kgs. Heavy polyethylene bag in a corrugated carton	
Shipment	Not dangerous goods. No special transport requirements.	
Storage Conditions	Storage temperatures should be kept below 30 C° and 50% relative humidity. Powder	
	should be stored in closed containers.	

DISCLAIMER: All the information given in this Data Sheet is the result of our research work experience. It is given in good faith and with every belief in its accuracy but cannot be considered as a formal warranty. In accordance with IBA KIMYA, policy of product development, this specification is subject to change without notice.